ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
3

Ward Name
Atturu

Street ID
W0789, W0556, W1083, W0829, W0807, W0825, W0813, W

Street Name
NA, 1st Main Rd

Significant Landmark
Sainagara and other area around Sambram Collage

Segment No.
3/C-W0789/S115623

Total Length (m)
401.38

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	272.72	77.546088	13.093587	77.548574	13.093215	M0005	W0853
2	128.66	77.544790	13.091820	77.545967	13.091675	W0789	M0005

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements To Roads and drains in Sainagara and other area around Sambram Collage in ward no 03 Yelahanka Satellite Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
1300000

Sanctioned Year
2015

Year
2016 - 2017

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements To Roads and drains in Sainagara and other area around Sambram Collage in ward no 03 Yelahanka Satellite Sub-Division Yelahanka zone

Job No. / Work Code
003-16-000017

Work Order No.
EE(YNK.D)/E-PMT-1/WO/42/2015-16

Work Order Date
27/02/2016

Period of Extention
90 DAYS

Defect Liability Period From
27/02/2016

Defect Liability Period To
26/02/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
K.GOPI REDDY

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Phone No.

E-Mail ID

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0789, W0556, W1083, W0829,

7760405418

Field Inspection Details

Number of Trees

6

Any Other Information

Name

PRADEEP

Date of Inspection

30/11/2016

Remarks

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	30/11/2016	29/12/2016	COMPLETED
SE	VASU K M	30/11/2016	29/12/2016	COMPLETED
EE	VASU K M	30/11/2016	29/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0789, W0556, W1083, W0829,